

Definition of Qualifiers:

XRF "J": A known standard is run at least 7 times during a batch run. The standard deviation (SD) is then calculated from those runs. The detection limit (DL) is equal to three times the SD and is therefore a statistical detection limit. This DL may or may not be achievable and consequently, confidence in results that are a little above the DL is not as high as results significantly above the DL. To represent this, results that are above the DL ($3 \times \text{SD}$) and 10 times the DL (known as the quantitation limit (QL) or reporting limit) are qualified with a "J" meaning estimated but still usable..

XRF "U": The element was not detected and the DL is listed. Due to the inherent interference between arsenic and lead, the arsenic DL is reported as the higher value between the statistical DL and one-tenth the lead result.

LAB "J": This qualifier could have been placed on the result by either the laboratory or the validator and represents that the value is estimated. The estimation could be due to any one or more of the following factors:

- On a sample by sample basis;
 - The value is above the DL and below the QL, similar to the XRF "J" qualifier above.
 - The result was above the calibration range.
- On a batch basis (a batch consisting of a maximum of 20 samples);
 - Interferences were present.
 - The spike recoveries were not within control limits. The result could be biased low or high depending on whether the spike recovery was low or high.
 - The duplicate analysis was not within control limits.
 - There was positive or negative blank contamination present resulting in an increase in the detection limit.

Luke -

Here are some more detailed definitions of the qualifiers. Once the lab results are validated there will probably be UJ and J present. Call me to discuss options after you look at these.

Rebecca

303 291 8229

Property Owner	MailingAddress	Town	State	ZipCode	Property	SampleCode	
Ex. 6 PP / Ex. 7(C)		Rico	Colorado	81332	Lot 38 Atlantic Cables	RAMIWL	
		Rico	Colorado	81332	113 & 115 N Silver Street	RASVCN	(970) 967-2105
		Rico	Colorado	81332	131 Garfield Street	RAGACN	"
		Rico	Colorado	81332	24 S Garfield Street	RAGACA	
		Rico	Colorado	81332	3 King Street	RAKICA	
					103 N Garfield Street	RAGAGA	(970) 967-2439
					214 E Mantz Avenue	RAMAHE	" 967-1508
					223 N River Street	RARIFE	
					32 N River Street	RARILE	" 967-2384
					226 S Argentine Street	RAARCR	
					118 Picker Street	RAPKCR	" 967-2625
					18 S Argentine Street	RAARWI	" 967-2945
					13 N Argentine Street	RAARHA	" 967-3504
					12 N Glasgow Street	RAGLLA	" 967-5440
					423 S Silverglance Way	RASIST	" 967-7910
					333 S Silverglance Way	RASIKI	
		Rico	Colorado	81332	101 N Hancock Street	RAHARO	
					124 N Hancock Street	RAHALI	
					33 N Hancock Street	RAHARE	
					11 S Commercial Street	RACOSH	
					14 S Commercial Street	RACOCA2	
					3 S Commercial Street	RACOAD	" 967-2003
					15 Silver Street	RASVFO	
		Flagstaff	Arizona	86004	Commercial Street	RACOCI	(602) 402-3512
		Rico	Colorado	81332	19 S Piedmont Street	RAPIME	
					203 S Silver Street	RASVKR	
		Rico	Colorado	81332	22 Sundial Way	RASNSE	
					Lot 2 Silverglance Way	RASICU	
		Dolores	Colorado	81323	1 Sundial Way	RASDGR	
		Rico	Colorado	81332	4 Picker Street	RAPKWT	
		Rico	Colorado	81332	12 W Eder Street	RAEDSF	
		Rico	Colorado	81332	3 S Picker Street	RAPKMI	
					213 S Commercial Street	RACQJN	
					217 Commercial Street	RACQCL	

Ex. 6 PP / Ex. 7(C)

<i>Gila Bend</i>	<i>AZ</i>	<i>85332</i>	219 Commercial Street	RACOWH	
			23 N Garfield Street	RAGAHQ	(528) 683-2892
			102 N Garfield Street	RAGADO	
Ft. Mohave	Arizona	86426	125 N Garfield Street	RAGAKZ	(928) 768-5589
			129 N Garfield Street	RAGAEN	
<i>Rice</i>	<i>CO</i>		16 Yellowman Street <i>Ave</i>	RAYEMU	
			8 Short Street	RASHBE	
Sandy	Utah	84070	12 Short Street	RASHCO	(801) 231-7708
			1 E Soda Street	RASOHE	(528) 526-2904
			3 E Soda Street	RASOBO	
			Argentine Street	RAARSC	
			1 & 3 Campbell Street	RACASC	
			12 S Argentine Street	RAARJO	
			34 River Street	RARIGS	
Rico	Colorado	81332	227 S Argentine Street	RAARCA	
			6 Soda Street	RASOIR	
Rico	Colorado	81332	24 Hinckley Drive	RAHICN	(970) 967-2105
			10036 Highway 145	RAHYFS	
			Park	RAARTP	
Rico	Colorado	81332	12 S Commercial Street	RACOCA1	
			5 Short Street	RASHDA	

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: Lot 38 Atlantic Cables

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NW of house in native soils	240	None	Depth Sample	RAMIWL1D1
Fill dirt around house	38 U	None	Surface Sample	RAMIWL1S1
Native soils from the N portion of the property	460	None	Surface Sample	RAMIWL1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 113 & 115 N Silver Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SE of house	1,800	1,900	Depth Sample	RASVCN1D1
Frontyard	2,700	None	Surface Sample	RASVCN1S1
Backyard	2,300	None	Surface Sample	RASVCN1S2
SW corner of property	2,700	2,800	Depth Sample	RASVCN2D1
N half of property	1,900	None	Surface Sample	RASVCN2S1
S half of property	2,400	None	Surface Sample	RASVCN2S2

PROPERTY: 131 Garfield Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of S half of property	1,000	1,300	Depth Sample	RAGACN1D1
S half of property	1,300	None	Surface Sample	RAGACN1S1
N half of property	1,300	1,400	Surface Sample	RAGACN1S2

PROPERTY: 24 Hinckley Drive

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NW of house	870	None	Depth Sample	RAHICN1D1
S half of property	1,300	None	Surface Sample	RAHICN1S1
N half of property	1,500	None	Surface Sample	RAHICN1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS

RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 12 S Commercial Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SW by trees	550	600	Depth Sample	RACOCA1D1
E half of prop	740	None	Surface Sample	RACOCA1S1
W half of prop	580	None	Surface Sample	RACOCA1S2

PROPERTY: 227 S Argentine Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Approximate center of property	1,700	2,700	Depth Sample	RAARCA1D1
N half of property	700	None	Surface Sample	RAARCA1S1
S half of property	570	None	Surface Sample	RAARCA1S2

PROPERTY: 24 S Garfield Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
E of house	960	None	Depth Sample	RAGACA1D1
SE of house	43 U	None	Depth Sample	RAGACA1D2
Yard	2,200	None	Surface Sample	RAGACA1S1
Bank surface	390	None	Surface Sample	RAGACA1S2

PROPERTY: 3 King Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NE corner of property	220 J	None	Depth Sample	RAKICA1D1
N half of property	300	None	Surface Sample	RAKICA1S1
S half of property	450	None	Surface Sample	RAKICA1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 103 N Garfield Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NE of house	530	None	Depth Sample	RAGAGA1D1
E half of property	630	None	Surface Sample	RAGAGA1S1
W half of property	300	610	Surface Sample	RAGAGA1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 214 E Mantz Avenue

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Excavation wall	520	None	Depth Sample	RAMAHE1D1
Front yard	710	None	Surface Sample	RAMAHE1S1
Backyard	1,000	None	Surface Sample	RAMAHE1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 223 N River Street

LEAD CONCENTRATIONS (mg/kg)					
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID	
Center of west yard	200 J	240	Depth Sample	RARIFE1D1	
East yard	330	None	Surface Sample	RARIFE1S1	
North yard	260 J	None	Surface Sample	RARIFE1S2	
West yard	340	None	Surface Sample	RARIFE1S3	

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 32 N River Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
By wood pile	820	None	Depth Sample	RARILE1D1
Front yard	1,000	None	Surface Sample	RARILE1S1
Backyard	570	None	Surface Sample	RARILE1S2
Garden	150 J	None	Surface Sample	RARILE1S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 226 S Argentine Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
E of southern trailer	82 U	59	Depth Sample	RAARCR1D1
E of southern trailer (discolored material)	1,400	None	Depth Sample	RAARCR1D2
Southern section	760	None	Surface Sample	RAARCR1S1
Center section (South Trailer)	640	None	Surface Sample	RAARCR1S2
North section (N trailer)	670	None	Surface Sample	RAARCR1S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 18 S Argentine Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of porch	2.700	4.400	Depth Sample	RAARWJ1D1
Inside fence	1.200	None	Surface Sample	RAARWJ1S1
E of house	4.100	None	Surface Sample	RAARWJ1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 13 N Argentine Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NE corner of residence	790	None	Depth Sample	RAARHA1D1
Section around residence (N half of property)	830	None	Surface Sample	RAARHA1S1
S half of property	180 J	None	Surface Sample	RAARHA1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS

RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 12 N Glasgow Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of shed	240	None	Depth Sample	RAGLLA1D1
S of driveway	3,100	None	Surface Sample	RAGLLA1S1
E of house	1,100	None	Surface Sample	RAGLLA1S2
Garden	110 J	None	Surface Sample	RAGLLA1S3
W of house	760	510	Surface Sample	RAGLLA1S4

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS

RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 423 S Silverglance Way

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of sample area RASIST1S2	86 J	None	Depth Sample	RASIST1D1
S half of property	260 J	None	Surface Sample	RASIST1S1
N half of property	230 J	None	Surface Sample	RASIST2S1
Fill around house	82 U	None	Surface Sample	RASIST3S1

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 333 S Silverglance Way

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NW of house	82 U	None	Depth Sample	RASIK11D1
S half of property	210 J	None	Surface Sample	RASIK11S1
N half of property	170 J	None	Surface Sample	RASIK11S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 101 N Hancock Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of house	2,900	4,300	Depth Sample	RAHARO1D1
Front of rock wall portion	5,000	5,400	Surface Sample	RAHARO1S1
Backyard	2,400	None	Surface Sample	RAHARO1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 124 N Hancock Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Front of house	82 U	None	Depth Sample	RAHALI1D1
Front driveway	230 J	None	Surface Sample	RAHALI1S1
Back wall	620	580	Surface Sample	RAHALI1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 33 N Hancock Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SW of house	3,600	4,100	Depth Sample	RAHARE1D1
Front yard	2,400	None	Surface Sample	RAHARE1S1
Sandbox	82 U	None	Surface Sample	RAHARE1S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 11 S Commercial Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of W half of property	510	None	Depth Sample	RACOSH1D1
E half of property	560	None	Surface Sample	RACOSH1S1
W half of property	490	None	Surface Sample	RACOSH1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 14 S Commercial Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
S of house	1500	None	Depth Sample	RACOCA2D1
W of house	550	None	Surface Sample	RACOCA2S1
E of house	850	None	Surface Sample	RACOCA2S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 3 S Commercial Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
E of shed	1,000	890	Depth Sample	RACOAD1D3
Front and side yards	790	None	Surface Sample	RACOAD1S1
Behind house	1,000	760	Surface Sample	RACOAD1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 15 Silver Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SE corner of property	150	None	Depth Sample	RASVFO1D1
N half of property	820	None	Surface Sample	RASVFO1S1
S half of property	360	None	Surface Sample	RASVFO1S2
SE of house	1,200	1,000	Depth Sample	RASVFO2D1
E of house	1,400	None	Surface Sample	RASVFO2S1
Rest of yard	1,500	1,300	Surface Sample	RASVFO2S2
SW of hotel	460	None	Depth Sample	RASVFO3D1
E of hotel	870	None	Surface Sample	RASVFO3S1
W of hotel	720	None	Surface Sample	RASVFO3S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: Commercial Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of property	450	None	Depth Sample	RACOC11D1
W half of property	850	None	Surface Sample	RACOC11S1
E half of property	790	None	Surface Sample	RACOC11S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 19 S Piedmont Street

LEAD CONCENTRATIONS (mg/kg)					
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID	
Behind house	89 J	None	Depth Sample	RAPIME1D1	
Backyard	65 J	None	Surface Sample	RAPIME1S1	
Front and side yards	150	None	Surface Sample	RAPIME1S2	

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 203 S Silver Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Between house and shed	84 J	None	Depth Sample	RASVKR1D1
E half of property	290	None	Surface Sample	RASVKR1S1
W half of property	78 J	None	Surface Sample	RASVKR1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS

RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: Lot 2 Silverglance Way

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of E half	82 U	None	Depth Sample	RASICUID1
E half of property	350	None	Surface Sample	RASICUIS1
W half of property	82 U	None	Surface Sample	RASICUIS2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: **Ex. 6 PP / Ex. 7(C)**

PROPERTY: 1 Sundial Way

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Between pines in sample area RASDGRIS7	38 U	15	Depth Sample	RASDGRID1
South of parking area	38 U	None	Surface Sample	RASDGRIS1
Between road and front yard	44 J	None	Surface Sample	RASDGRIS2
Front yard	38 U	None	Surface Sample	RASDGRIS3
Garden	38 U	None	Surface Sample	RASDGRIS4

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 4 Picker Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SE corner of property	160	None	Depth Sample	RAPKWT1D1
N half of property	160	None	Surface Sample	RAPKWT1S1
S half of property	400	None	Surface Sample	RAPKWT1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS

RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 12 W Eder Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SW of property	730	None	Depth Sample	RAEDSF1D1
W half of property	120 J	None	Surface Sample	RAEDSF1S1
E half of property	300	None	Surface Sample	RAEDSF1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 3 S Picker Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of house	38 U	99	Depth Sample	RAPKMIID1
S half of property	170	None	Surface Sample	RAPKMIIS1
N half of property	600	None	Surface Sample	RAPKMIIS2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 213 S Commercial Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NE of house	180	None	Depth Sample	RAC0JN1D1
S & W of house	210	None	Surface Sample	RAC0JN1S1
E half of property	520	410	Surface Sample	RAC0JN1S2
Playground	340	None	Surface Sample	RAC0JN1S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 217 Commercial Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Immediately S of house	500	None	Depth Sample	RACOCL1D1
S of house	330	None	Surface Sample	RACOCL1S1
W of house	130	None	Surface Sample	RACOCL1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 219 Commercial Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
E of house	240	None	Depth Sample	RACOWH1D1
N and S of house	360	None	Surface Sample	RACOWH1S1
NE portion of property	820	600	Surface Sample	RACOWH1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 23 N Garfield Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NE of tree	500	None	Depth Sample	RAGAH01D1
E of house	170	None	Surface Sample	RAGAH01S1
W of house	230	310	Surface Sample	RAGAH01S2
N of driveway	1,500	None	Surface Sample	RAGAH01S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 102 N Garfield Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Between walkway and house	2.600	2.900	Depth Sample	RAGADO1D1
E & N of house	1.200	None	Surface Sample	RAGADO1S1
W of house	2.300	None	Surface Sample	RAGADO1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 125 N Garfield Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
E of garden	520	None	Depth Sample	RAGAKZ1D1
S half of property	670	None	Surface Sample	RAGAKZ1S1
N half of property	1,100	None	Surface Sample	RAGAKZ1S2
Garden composite	700	None	Surface Sample	RAGAKZ1S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 129 N Garfield Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NE of shed	1,400	1,500	Depth Sample	RAGAEN1D1
S half of property	850	None	Surface Sample	RAGAEN1S1
N half of property	1,900	None	Surface Sample	RAGAEN1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 16 Yellowman Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
S corner of property	1.500	1.800	Depth Sample	RAYEMU1D1
S half of property	1.500	None	Surface Sample	RAYEMU1S1
N half of property	1.400	None	Surface Sample	RAYEMU1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 8 Short Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of shed	450	None	Depth Sample	RASHBE1D1
S half of property	1,300	None	Surface Sample	RASHBE1S1
N half of property	1,400	None	Surface Sample	RASHBE1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 12 Short Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of sample area RASHCO1S2	1.200	1.300	Depth Sample	RASHCO1D1
W Half of property	2.200	2.000	Surface Sample	RASHCO1S1
E half of property	2.000	None	Surface Sample	RASHCO1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 1 E Soda Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W edge of undeveloped property	9.200	7.400	Depth Sample	RASOHE1D1
S half of property	300	None	Surface Sample	RASOHE1S1
N half of property	18.000	41.000	Surface Sample	RASOHE1S2
Undeveloped, N of residence	2.300	None	Surface Sample	RASOHE1S3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS
RICO, COLORADO

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 3 E Soda Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NW of house	1,800	1,900	Depth Sample	RASOBO1D1
E half of property	550	440	Surface Sample	RASOBO1S1
W half of property	1,200	None	Surface Sample	RASOBO1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

SOIL SAMPLE RESULTS RICO, COLORADO

PROPERTY OWNER: Dolores County School

PROPERTY: 1 & 3 Campbell Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of house	370	None	Depth Sample	RACASC1D1
W half of prop	770	None	Surface Sample	RACASC1S1
E half of prop	610	None	Surface Sample	RACASC1S2
NE corner	490	None	Depth Sample	RACASC3D1
W half of property	710	None	Surface Sample	RACASC3S1
E half of property	490	None	Surface Sample	RACASC3S2
Sandbox	82 U	None	Surface Sample	RACASC3S3

PROPERTY: Argentine Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NW corner of prop	510	None	Depth Sample	RAARSC1D1
E half of property	920	None	Surface Sample	RAARSC1S1
W half of property	510	440	Surface Sample	RAARSC1S2

PROPERTY: School Playground/Town Park

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
NW part of prop	1,500	2,300	Depth Sample	RAARTP1D1
N half of property	570	None	Surface Sample	RAARTP1S1
S half of property	820	None	Surface Sample	RAARTP1S2
Sandbox	82 U	None	Surface Sample	RAARTP1S3
Volleyball court	82 U	None	Surface Sample	RAARTP1S4

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 12 S Argentine Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
SW of residence	280	None	Depth Sample	RAARJO1D1
N half of property	390	None	Surface Sample	RAARJO1S1
S half of property	970	None	Surface Sample	RAARJO1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 34 River Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Between garden and house	610	None	Depth Sample	RARIGSID1
Backyard	1,300	None	Surface Sample	RARIGSIS1
Front yard	1,300	None	Surface Sample	RARIGSIS2
Garden	850	700	Surface Sample	RARIGSIS3

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 6 Soda Street

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
W of shed	520	450	Depth Sample	RASOIR1D1
W half of property	680	None	Surface Sample	RASOIR1S1
E half of property	670	None	Surface Sample	RASOIR1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: United States Forrest Service

PROPERTY: 10036 Highway 145

LEAD CONCENTRATIONS (mg/kg)

Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Aspen grove	43 J	52	Depth Sample	RAHYFS1D1
Aspen grove	85 J	None	Surface Sample	RAHYFS1S1
Front and rear of station	47 J	None	Surface Sample	RAHYFS1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.

**SOIL SAMPLE RESULTS
RICO, COLORADO**

PROPERTY OWNER: Ex. 6 PP / Ex. 7(C)

PROPERTY: 5 Short Street

LEAD CONCENTRATIONS (mg/kg)				
Sample Location	Field Analytical Results	Laboratory Analytical Results	Sample Description	Sample ID
Center of sample area RASHDA1S1	460	550	Depth Sample	RASHDA1D1
W half of property	1,100	None	Surface Sample	RASHDA1S1
E half of property	1,700	None	Surface Sample	RASHDA1S2

U - The analyte was not detected above the detection limit. The detection limit is reported.

J - The associated numerical value is an estimated quantity between the detection limit and the quantitation limit.